PRODUCT INFORMATION

Replacement for Onan® P/N 332-I956 VR2I Regulator Control Board (ASAP P/N VR332I956)



LIST OF FEATURES:

- Mounting footprint and terminal locations identical to original board. No modification required to install.
- Heavy conformal coating applied for moisture and vibration resistance.
- Upgraded components used throughout the board.
- User-replaceable fuses.
- Rugged barrier strip and improved, more durable power resistors.

MAINTENANCE SUGGESTION:

When replacing control board we also recommend replacing SCR Pack to ensure proper operation. (Stocked by ASAP: P/N BRP405W)



1051 E Cumberland St, Lebanon, PA 17042

www.partsfortechs.com

Technical Support:

717-383-4982 (8-4:00 ET, M-F) Fax: 877-679-7644